R Ø82125Z JAN 69 FM NPIC WASHDC TO RUEOJFA/DIA RUEFHQA/HQ USAF RHCOAAA/SAC OFFUTT AFB RUEOJFA/JCS (JRC) S E C R E T CITE NPIC 5425 DIA FOR DIAXX-2; HQ USAF FOR AFRDR, AFNIN, AFXOPR; SAC FOR DIR; SUBJECT: EVALUATION OF THREE BOQ MISSIONS REFS: A. DIAXX-24452 5 NOV 68 В. NPIC 5153 3 DEC 68

THE FOLLOWING MISSIONS WERE EVALUATED: MISSION DATE FLOWN VEHICLE CAMERA 30 SEPT 68 H-55 Q-224

Q-242

5 OCT 68 H-3 65 9 DEC 68 H-58 SCORER 1 0-243

2. CLOUDS AND HAZE OBSCURE OR DEGRADE APPROXIMATELY 40 PERGISHRIBUTION OF EACH MISSION.

3. QUALITY SUMMARY:

PAGE 2 RUEADJU 0032 S E C R E T

A. COMMENTS APPLICABLE TO ALL MISSIONS:

(1) BANDING - PRESENT ON ALL MISSIONS.

DENSITY - ADEQUATE ON ALL MISSIONS EXCEPT IN (2)

VEILED PORTIONS OF THE MISSIONS.

(3) VEILING - SMILAR TO THAT NOTED ON RECENT MISSIO OF THIS TYPE. FRAMES EXPOSED IN THE 1L AND 1R POSITIONS ARE MOST SEVERELY DEGRADED. IN EACH CASE, THE DEGRADATION IS MORE SEVERE ON THE LAST THREE QUARTERS OF THE MISSION THAN ON THE FIRST QUARTER. IT SEEMS PROBABLE THAT THIS DEGRADATION IS CAUSED BY CONDENSATIONS ON THE FORWARD EDGES OF THE WINDOW.

B. COMMENTS APPLICABLE TO INDIVIDUAL CAMERAS:

(1) Q-224, 3Ø SEPT 68: BANDING IS MORE SEVERE THAN ON OTHER MISSIONS. THE FIRST THREE INCHES, WHEN THE SHUTTER MOVED TOWARD SUPPLY, ARE MOST SEVERELY DEGRADED.

(2) Q-242, 5 OCT 68: THE INCORRECT DATA (8 OCT 68) IS ON THE LABEL OF EACH CAN. SEVERE PHYSICAL DAMAGE WAS NOTED THROUGHOUT. APPARENTLY, THE LACQUER FROM TITLING WAS NOT DRY BEFORE THE FILM WAS SPOOLED. IT THEN CAUSED LARGE EMULSION LIFTS AND TEARS WHEN THE FILM WAS UNROLLED.

	Problem	-4
	SECUR.	_ _
34	TSSU/A/SDL	1
1		_
	250/00	_
	RRD	_
VIC.	KEI RO	
TO	AID	_
	LEG	_
	FROD	_
	SCIEN	
	WEST	_
	EAST	-#
	HAS meaning in	}
	JAN TANK	- 1
	IA5	- 3
	DIA-XXX	
	SPAD	s
	DIAMA	
-	25)	<b>1</b>
	CMX	
		z
	The state of the s	•

OFFICE

FILE CARGE

PAGE 3 RUEADJII ØØ3	32 SECRET	SANTIZED
4.		WAS ALSO EVALUATED. 25X1
THE GROUND RESOLUT	TION IS SLIGHTLY BETTER T	HAN THE OPERATIONAL MISSIONS.

VEILING IS NOT AS EVIDENT AS ON EACH OPERATIONAL MISSION. SUGGEST THAT THE PREFLIGHT PROCEDURES AND VEHICLE PARAMETERS OF THESE MISSIONS BE COMPARED IN AN ATTEMPT TO EXPLAIN THIS APPARENT ABSENCE OF VEILING.

6. THIS COMPLETES THE REQUIREMENTS LEVIED BY REF A. REF B DESCRIBES THE RESULTS OF THE FIRST PORTION OF THIS ANALYSIS.

GP-1 - S E C R E T - END OF MS

GROUP 1 **Excluded** from automati downgrading and declassification

×

25X1